

Division of Oil, Gas, & Mining
Mining Report

03/01/96

MINE ID: M0370044

MINE NAME: CUB MINE

OPERATOR: KELMINE CORPORATION
CONTACT: MELVIN R SWANSON
ADDRESS: 2051 SWANSON CIR
MOAB UT 84532

PHONE: (801)259-6867

Surface Owner: BLM
Mineral Owner: BLM

BLM #:
Lease #:

Qtr-Qtr-Qtr1	Qtr-Qtr1	Qtr1	Qtr-Qtr-Qtr2	Qtr-Qtr2	Qtr2	Sec	Town	Range
	SE	SE				26	30.0S	25.0E

Permit Status: APP

Mine Type [(S)urface, (U)nderground]: U

Mine Status: SUS

Acreage: 0

Status Date: / /

Minerals Mined
U

DATE
RECEIVED

TENTATIVE APPROVAL
DATE

FINAL APPROVAL
DATE

LAST INSPECTED

04/19/79

07/26/79

09/07/79

11/02/95

BOND TYPE: SURETY BOND

BOND AMOUNT: \$\$\$\$11,008

ANNUAL REPORT YEAR: 95

	YTD	Total			
NONCOMP NOTICES:	0	0	DATE ISSUED:	/ /	DATE RESOLVED: / /
VIOLATIONS:	0	0	DATE ISSUED:	/ /	DATE RESOLVED: / /
REVISIONS:	0	0	DATE REC'D:	/ /	DATE APPROVED: / /
AMENDMENTS:	0	1	DATE REC'D:	09/30/92	DATE APPROVED: 11/04/92

COMMENTS:

RECLAMATION EVALUATION INSPECTION MADE 7/93. TWO AREAS HAVE BEEN RECLAIMED; THE LOWER AREA & UPPORT PORTION. THE LOWER PORTION, CONSISTING OF A PORTAL, WASTE DUMPS & OFFICE COMPLEX HAVE BEEN ADEQUATELY RECLAIMED. THE UPPER PORTION CONSISTS OF A VENT SHAFT & FAN WORKING. ONE AREA THE BLM IS CONCERNED WITH IS A PRE-LAW SHAFT THAT WAS NOT RECLAIMED (WAS NOT PART OF ORIGINAL NOTICE). BLM TO CONTACT CLAIM HOLDER TO RECLAIM IT. THE ROAD NEEDS RECLAIMED & SEEDED, POWER POLE FROM TOP OF VENT SHAFT NEEDS REMOVED BY UP&L. (@.6 ACRES STILL NEEDS WORK)